

WO #: PE49922

WO Desc: m1 supply valve leaking

Parent WO#:

WO Long Desc:

WO Priority: 1

Location: E-T-R18C

REACTOR 18 CATALYST TANK - 6TH FLOOR

Asset: 1347971

REACTOR 18 CATALYST TANK - 6TH FLOOR

Asset Service:

Entry Date: 1/2/2014

WO Status: CLOSE

Action Code: LDAR

Project #:

Originator: DEMETRIO SALAZAR

Status Date: 7/2/2014

Work Type: CM

Failure Class: TANK

Job Plan:

Planned Start:

Actual Start: 1/2/2014

Review Date:

PM/Bundle:

Planned Completion:

Actual Completion: 1/2/2014

Plant Information

RC: PERC01

Planner: WILLIAM STONEKING

MOC#:

When Code: RT

Lead Craft: MECH

MOC Status:

P&ID:

MOC Desc:

SIR/EIS Required:

LDAR

Tag #:

1st Attempt Made:

LDAR Planning Notes:

Leak Type:

1st Attempt Was:

LDAR Additional Notes:

Size:

1st Attempt Due By: 1/7/2014

Leak Location:

After 1st Attempt PPM:

Location Orientation:

Final Due By: 1/17/2014

Work Actuals Materials

Task ID	Stock No.	Noun Qualifier	PO	PO Line Num	Quantity
	401199	KIT, REBUILD, APOLLO BALL VALVE, 1", SS, SW			1

Work Order Notes

JOSEPH VITTONI

01/02/2014 Rebuilt valve.

Completed by Emp #: _____

Signature: _____